




Replaces Exmark Pioneer E-Series Parts

Zero-Turn Mower with 52 in Deck - Models

PNE691GKA52200 & PNE720GKC52200

52in Deck



All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.



Replaces Exmark Pioneer E-Series Parts

Zero-Turn Mower with 52 in Deck - Models
PNE691GKA52200 & PNE720GKC52200
52in Deck



| Item No | R&R Part No. | OEM Part No. | Description | Qty Req | Order Quantity |
|---|---------------------|--------------------------------------|--|---------|----------------|
| Rotary Blades | | | | | |
| 1 | R116-5175 | 116-5175 | Mower Blade - 18 in Mulching | 3 | |
| 1 | RRB4065-1803 | 116-5175, 116-5175-S | Mower Blade - Mulcher 18 x 2.5in x 15/16 Mt Hole | 3 | |
| 2 | RRB3065-1803 | 103-6402, 103-6402-S, 106-6402 | Mower Blade - High-Lift 18 x 2.5in x 15/16 Mt Hole | 3 | |
| <i>Detail Description: R&R Products rotary blades are manufactured in the USA with superior alloy steel and hardened for extended life. Lifetime guaranteed against defects in material and workmanship.:</i> | | | | | |
| Belts | | | | | |
| 20 | R115-9613 | 115-9613 | Belt - Cogged V | 1 | |
| Other Parts Available | | | | | |
| 40 | R116-4669 | 116-4669 | Idler Pulley - Flat | 1 | |
| 41 | R1-633447 | 1-633447 | Chain - Deck Lift | 4 | |
| 42 | R116-6317 | 116-0133, 116-6317 | Spring - Extension | 1 | |
| 43 | R104-8301 | 104-8301, 109-6658 | Locknut - 3/8-16 Nylon Flanged | 3 | |
| 44 | R116-8131 | 116-8131 | Axle - Roller | 3 | |
| 45 | R98-5975 | 98-5975 | Washer - Belleville | 3 | |
| 46 | R116-9981 | 116-9981 | Kit - Anti-Scalp Roller | 3 | |
| 47 | R103-8415 | 103-8415 | Roller - Anti Scalp | 3 | |
| 48 | R3219-6 | 3219-6 | Nut - 5/8-18 Gr 8 Hex | 3 | |
| 49 | R116-1947X | 116-1947 | Xtreme Pto Clutch | 1 | |

All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.



Replaces Exmark Pioneer E-Series Parts

Zero-Turn Mower with 52 in Deck - Models

PNE691GKA52200 & PNE720GKC52200

52in Deck



| Item No | R&R Part No. | OEM Part No. | Description | Qty Req | Order Quantity |
|--|------------------|--------------|-------------------------------------|---------|----------------|
| <i>Tech Note: Use only for model PNE720GKC52200:</i> | | | | | |
| 50 | R116-2456 | 116-2456 | Pulley - Flat Idler w/Bushing | 2 | |
| 53 | R116-0005 | 116-0005 | Bolt- Blade, - Sems 7/16-20 | 3 | |
| 54 | R116-9362 | 116-9362 | Bolt - Hex HD 3/8-16 x 3 3/4 GR8 YZ | 3 | |

All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.