



# Replaces Toro Groundsmaster 7210

## Parts

Zero-Turn Mower with 72in Deck - Model 30619  
Seat



All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.



# Replaces Toro Groundsmaster 7210 Parts

Zero-Turn Mower with 72in Deck - Model 30619  
Seat



| Item No | R&R Part No. | OEM Part No. | Description | Qty Req | Order Quantity |
|---------|--------------|--------------|-------------|---------|----------------|
|---------|--------------|--------------|-------------|---------|----------------|

## Electrical and Guages

|    |                  |   |                             |   |  |
|----|------------------|---|-----------------------------|---|--|
| 60 | <b>R93-9999</b>  | 93-9999   | Switch - Pto                | 1 |  |
| 61 | <b>R104-2541</b> | 104-2541,<br>88-9830  | Switch - Key 6 Lead 5/8 Mt. | 1 |  |
| 62 | <b>R343060</b>   | 218-412,<br>32-8380,<br>33-2010,<br>62-7770,<br>63-8360,<br>94-2618 | Ignition - Key Set/2        | 1 |  |
| 63 | <b>R150229</b>   | 82-2190   | Switch - Operator Presence  | 1 |  |
| 64 | <b>R108-8657</b> | 108-8657  | Harness-Wire, Seat          | 1 |  |

## Other Parts Available

|    |                  |   |                                  |   |  |
|----|------------------|---|----------------------------------|---|--|
| 70 | <b>R150848</b>   | 100-4928,<br>106-7848,<br>110-0413,<br>110-9720,<br>95-8910 | Belt-Seat                        | 1 |  |
| 71 | <b>R3212-4</b>   | 3212-3,<br>3212-4,<br>3212-5                                | Bolt - Hex HD 7/16-20 x 1 GR5    | 2 |  |
| 72 | <b>R187-0</b>    | 3256-25,<br>7-0032  | Washer - Flat 7/16 SAE           | 2 |  |
| 73 | <b>R99-7667</b>  | 99-7667   | Washer - Flat 5/8                | 2 |  |
| 74 | <b>R74-5950</b>  | 249-48,<br>74-5950  | Latch - Swell                    | 2 |  |
| 75 | <b>R104-8300</b> | 104-8300,<br>104-8300 ,<br>119-4041                         | Locknut - 5/16-18 Flanged Y/Zinc | 6 |  |
| 76 | <b>R2412-133</b> | 01-651-0160,<br>2412-133                                    | Clamp                            | 2 |  |

All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.



# Replaces Toro Groundsmaster 7210 Parts

*Zero-Turn Mower with 72in Deck - Model 30619  
Seat*



| Item No | R&R Part No.     | OEM Part No.       | Description                   | Qty Req | Order Quantity |
|---------|------------------|--------------------|-------------------------------|---------|----------------|
| 77      | <b>R3230-23</b>  | 3230-23,<br>Mar-61 | Bolt - 5/16-18x3/4 - Carriage | 2       |                |
| 78      | <b>R283-55</b>   | 283-55             | Clevis Pin - 1/2 x 3          | 2       |                |
| 79      | <b>R104-7201</b> | 104-7201           | Locknut - 1/4-20 ESNA Flanged | 2       |                |
| 80      | <b>R240-14</b>   | 240-14,<br>92-5979 | Bumper - Rubber               | 2       |                |
| 81      | <b>R1-633268</b> | 1-633268           | Grip - Lever - Foam           | 1       |                |

All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.