




Replaces Toro Groundsmaster 7210 Parts

Zero-Turn Mower with 72in Deck - Model 30619
Hydraulic Assembly



All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.



Replaces Toro Groundsmaster 7210 Parts

Zero-Turn Mower with 72in Deck - Model 30619
Hydraulic Assembly



| Item No | R&R Part No. | OEM Part No. | Description | Qty Req | Order Quantity |
|---------|--------------|--------------|-------------|---------|----------------|
|---------|--------------|--------------|-------------|---------|----------------|

Other Parts Available

| | | | | | |
|--|-------------------|--|---------------------------|---|--|
| 70 | R2412-34 | 2412-34, 31-0120 | Clamp - Hose .75-1.5 | 2 | |
| <i>Detail Description: Stainless steel hose clamp with 5/16" slotted hex head, heat treated carbon steel, plated with zinc plus trivalent chromate for long lasting protection.:</i> | | | | | |
| 71 | R104-7546 | 104-7546, 104-7546` | Strainer - Tank | 1 | |
| 72 | R340-136 | 340-136 | O-Ring | 1 | |
| 73 | R237-42 | 237-42, 31-4160 | O-Ring | 2 | |
| 74 | R353-989 | 353-989 | Plug - Hex - Hollow | 1 | |
| 75 | R93-7498 | 93-7498 | Plug-Oil | 1 | |
| 76 | R354-73 | 354-73 | Fitting-Straight | 1 | |
| 77 | R2412-129 | 2412-129, 94-3188, 94-3189, 94-3193, 94-3203, 94-3204 | Clamp - Worm 9/16-1 1/4 | 4 | |
| 78 | R46-6550 | 46-6550 | Fitting - Elbow 90 | 1 | |
| 79 | R46-6560 | 46-6560 | Bushing | 2 | |
| 80 | R2412-98 | 2412-98 | Clamp - Spring - Hose 1/4 | 2 | |
| 81 | R32180-030 | 32180-030 | Clip-Harness | 1 | |
| 82 | R92-2379 | 92-2379 | Clamp - Hose | 2 | |
| 83 | R3290-379 | 3290-336, 3290-379 | Cable Tie - 6in | 2 | |
| 84 | R68-6150 | 58-9070, 68-6150 | Breather | 1 | |

All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.



Replaces Toro Groundsmaster 7210 Parts

Zero-Turn Mower with 72in Deck - Model 30619
Hydraulic Assembly



| Item No | R&R Part No. | OEM Part No. | Description | Qty Req | Order Quantity |
|---------|------------------|------------------------------|------------------------------------|---------|----------------|
| 85 | R2412-108 | 2412-108, 97406 | Clamp - Worm - 1/4 - Stainless | 2 | |
| 86 | R353-979 | 353-979 | Fitting - Straight | 1 | |
| 87 | R237-30 | 23-6320, 237-30 | O-Ring - Seal | 1 | |
| 88 | R340-4 | 340-4 | Hydraulic Fitting - Male Connector | 1 | |
| 89 | R237-79 | 237-79 | O-Ring | 1 | |
| 90 | R237-65 | 237-65, 237.65 | O-Ring | 1 | |
| 91 | R340-7 | 340-7 | Adapter | 1 | |
| 92 | R237-80 | 237-80, 327-80 | O-Ring | 1 | |
| 93 | R237-81 | 237-81, 237.81, 327-81 | O-Ring | 1 | |
| 94 | R353-987 | 353-987 | Hydraulic Fitting - 90 Deg | 2 | |

All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.