



NGK Spark Plug - BZ7HS-10

RN3579



Replaces

Champion	5828, 5883, 828-1, 828M, 828S, 831-1, 831S, 8883, 8883-2, 938-1, 938M, 938S, QL77J4, QL77JC4
----------	--

Specifications

Manufacturer	NGK
Box Quantity	10
Package Quantity	1

Japan Equipment

123 Main St. Apartment 12 Tokyo, 100-0001
987-456-3210

<https://japan.rrproducts.com/>