




# Replaces Toro Groundsmaster 4010-D Parts

Rotary Mower - Model 30446  
Side Deck Lift Arm and Damper



All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.



# Replaces Toro Groundsmaster 4010-D Parts

Rotary Mower - Model 30446  
Side Deck Lift Arm and Damper



| Item No | R&R Part No. | OEM Part No.                                                                                                                                   | Description                     | Qty Req | Order Quantity |
|---------|--------------|------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------|---------|----------------|
| 1       | R108-1471    | 105-2800,<br>108-1471                                                                                                                          | Rear Arm Assy - RH              | 1       |                |
| 1       | R108-1473    | 105-2801,<br>108-1473                                                                                                                          | Rear Arm Assy - LH              | 1       |                |
| 2       | R256-113     | 256-113                                                                                                                                        | Bushing - 3/4 ID x 1 1/8 Flange | 4       |                |
| 3       | R302-5       | 21-6010,<br>302-11,<br>302-37,<br>302-47,<br>302-5,<br>302-57,<br>302-58,<br>302-6,<br>31-0300,<br>32-9660,<br>60-0800,<br>62-3880,<br>92-4181 | Fitting - Grease                | 2       |                |
| 4       | R108-1476-03 | 100-5690-03,<br>108-1476-03,<br>114-2717                                                                                                       | LH Bell Crank Assy              | 1       |                |
| 4       | R108-1475-03 | 100-5684-03,<br>108-1475-03,<br>114-2716                                                                                                       | RH Bell Crank Assy              | 1       |                |
| 5       | R105-3249    | 104-7512,<br>105-3249                                                                                                                          | Damper                          | 2       |                |
| 6       | R105-2809    | 105-2809                                                                                                                                       | Tube - Link                     | 2       |                |
| 7       | R104-7520    | 104-7520                                                                                                                                       | Spring - Damper                 | 2       |                |
| 8       | R105-2807-03 | 105-2807-03                                                                                                                                    | Plate                           | 2       |                |
| 9       | R104-8348    | 104-8348                                                                                                                                       | Plate-Rubber                    | 2       |                |
| 10      | R108-1528-03 | 108-1528-03                                                                                                                                    | Plate                           | 2       |                |
| 11      | R114-5640-03 | 114-5640-03                                                                                                                                    | Yoke - Joint Assy w/Bearing     | 2       |                |

All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.



# Replaces Toro Groundsmaster 4010-D Parts

Rotary Mower - Model 30446  
Side Deck Lift Arm and Damper



| Item No                                          | R&R Part No.     | OEM Part No.                          | Description                  | Qty Req | Order Quantity |
|--------------------------------------------------|------------------|---------------------------------------|------------------------------|---------|----------------|
| <i>Tech Note: Fits Models 30446 &amp; 30448:</i> |                  |                                       |                              |         |                |
| 12                                               | <b>R104-4299</b> | 104-4299                              | Cross and Bearing            | 1       |                |
| 13                                               | <b>R104-2281</b> | 104-2281                              | Shaft- Pivot                 | 2       |                |
| 14                                               | <b>R32120-93</b> | 32120-93                              | Snap Ring - HD               | 2       |                |
| 15                                               | <b>R3272-25</b>  | 01-151-0020,<br>3272-25               | Pin-Cotter                   | 2       |                |
| 16                                               | <b>R104-0720</b> | 104-0720                              | Spacer                       | 2       |                |
| 17                                               | <b>R104-8331</b> | 104-8331                              | Rod End - Spherical          | 4       |                |
| 19                                               | <b>R100-8138</b> | 100-8138                              | Spring-Compression           | 2       |                |
| 20                                               | <b>R105-4548</b> | 105-4548                              | Shaft - Spring               | 2       |                |
| 21                                               | <b>R105-4552</b> | 105-4552                              | Bearing - Plastic            | 2       |                |
| 22                                               | <b>R105-4550</b> | 105-4550                              | Bushing - Straight           | 2       |                |
| 23                                               | <b>R105-2806</b> | 105-2806                              | Rod End                      | 2       |                |
| 24                                               | <b>R105-2808</b> | 105-2808                              | Rod End                      | 4       |                |
| 25                                               | <b>R328-5</b>    | 01-150-0690,<br>01-178-1228,<br>328-5 | Bolt - Hx HD 3/4-10 x 3 1/2  | 2       |                |
| 26                                               | <b>R3296-51</b>  | 3296-51,<br>3296-81                   | Nut - Nylon Lock 3/4-10 Gr 8 | 2       |                |
| 27                                               | <b>R92-2739</b>  | 92-2739                               | Pin - Clevis                 | 2       |                |
| 28                                               | <b>R104-8341</b> | 104-8341                              | Bushing - 1 1/4 in Straight  | 4       |                |
| 28                                               | <b>R114-5596</b> | 114-5596                              | Bushing - 1 in Straight      | 4       |                |
| 29                                               | <b>R99-3139</b>  | 99-3139,<br>Nov-00                    | Nut                          | 2       |                |

All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.



# Replaces Toro Groundsmaster 4010-D Parts

*Rotary Mower - Model 30446  
Side Deck Lift Arm and Damper*



| Item No | R&R Part No.     | OEM Part No.                                                                | Description                  | Qty Req | Order Quantity |
|---------|------------------|-----------------------------------------------------------------------------|------------------------------|---------|----------------|
| 30      | <b>R3290-467</b> | 3290-467                                                                    | Pin-Hair                     | 2       |                |
| 31      | <b>R3-6498</b>   | 3--6498,<br>3-6498,<br>47-8270                                              | Washer - Thrust              | 4       |                |
| 32      | <b>R104-0721</b> | 104-0721                                                                    | Washer - Thrust              | 4       |                |
| 33      | <b>R3296-29</b>  | 1-804256,<br>3290-357,<br>3296-29,<br>915662P                               | Locknut - 5/16-18 ESNA       | 6       |                |
| 34      | <b>R119-0089</b> | 119-0089                                                                    | LH Lift Arm Assy             | 1       |                |
| 34      | <b>R119-0087</b> | 119-0087                                                                    | RH Lift Arm Assy             | 1       |                |
| 35      | <b>R104-0719</b> | 104-0719                                                                    | Washer - Hardened            | 2       |                |
| 36      | <b>RF104</b>     | 01-166-0020,<br>01-166-1010,<br>23-15-GD,<br>30-8480,<br>3253-8,<br>48-9400 | Washer - Lock 5/8            | 2       |                |
| 37      | <b>R3296-53</b>  | 3296-53                                                                     | Locknut - 5/8-11 ESNA Yellow | 2       |                |
| 38      | <b>R322-10</b>   | 20-30-AD,<br>24-7180,<br>322-10,<br>322-10 ,<br>3223-6,<br>513347           | Bolt - Hex HD 5/16-18 x 2    | 4       |                |
| 39      | <b>R105-4551</b> | 105-4551                                                                    | Washer- Flat                 | 4       |                |
| 40      | <b>RF5003</b>    | 32127-29,<br>32131-5,<br>32132-5,<br>3296-23                                | Locknut - ESNA 1/2-13        | 6       |                |
| 41      | <b>R104-7521</b> | 104-7521                                                                    | Bushing                      | 4       |                |

All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.



# Replaces Toro Groundsmaster 4010-D Parts

*Rotary Mower - Model 30446  
Side Deck Lift Arm and Damper*



| Item No | R&R Part No. | OEM Part No.                                                                                                              | Description                    | Qty Req | Order Quantity |
|---------|--------------|---------------------------------------------------------------------------------------------------------------------------|--------------------------------|---------|----------------|
| 42      | R3229-1      | 01-173-0406,<br>01-178-0408,<br>3229-1,<br>3229-25,<br>900015P                                                            | Bolt - 1/4-20 x 3/4 - Carriage | 4       |                |
| 43      | R3256-26     | 01-166-0540,<br>01-166-0820,<br>17-2530,<br>24-13-BD,<br>30-8570,<br>3256-26,<br>356206,<br>48-9390                       | Washer - 1/2 in                | 26      |                |
| 44      | R3296-39     | 32127-25,<br>32128-36,<br>3290-357,<br>3296-17,<br>3296-22,<br>3296-39,<br>915663P,<br>99-7443                            | Locknut - 3/8-16 Nylon         | 8       |                |
| 45      | RMM607       | 01-158-0610,<br>01-191-0820,<br>21-3900,<br>3220-5,<br>45-0170,<br>5/1/3220                                               | Nut - Jam 1/2-20 Zinc          | 2       |                |
| 46      | R400264      | 01-150-0180,<br>01-178-0610,<br>20-48-AD,<br>20-48-AGD,<br>32-9160,<br>3224-3,<br>323-29,<br>323-7,<br>400264,<br>908035P | Bolt - Hex HD 3/8-16 x 1-1/4   | 8       |                |
| 47      | R443118      | 01-188-0813,<br>22-15-AJD,<br>3217-9                                                                                      | Nut - 1/2-13 Zinc              | 4       |                |

All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.



# Replaces Toro Groundsmaster 4010-D Parts

Rotary Mower - Model 30446  
Side Deck Lift Arm and Damper



| Item No | R&R Part No. | OEM Part No.                                                                                               | Description                    | Qty Req | Order Quantity |
|---------|--------------|------------------------------------------------------------------------------------------------------------|--------------------------------|---------|----------------|
| 48      | R3253-7      | 01-166-0030,<br>01-166-0080,<br>01-166-0290,<br>01-166-0810,<br>23-13-GD,<br>3253-7,<br>48-9380            | Washer - Lock 1/2              | 8       |                |
| 49      | R3220-7      | 01-191-1216,<br>3220-7,<br>Mar-03                                                                          | Nut - 3/4-16 Jam Zinc          | 2       |                |
| 50      | R301504      | 2296-42,<br>301504,<br>32127-24,<br>32128-33,<br>32146-17,<br>3296-16,<br>3296-42,<br>3296-42 ,<br>915661P | Locknut - ESNA 1/4-20          | 6       |                |
| 51      | R119-0117-03 | 119-0117-03                                                                                                | Mount- Bumper - LH             | 1       |                |
| 51      | R119-0116-03 | 119-0116-03                                                                                                | Mount- Bumper - RH             | 1       |                |
| 52      | R322-13      | 01-150-1680,<br>01-178-0522,<br>322-13,<br>3223-9                                                          | Screw - Hxx HD                 | 2       |                |
| 53      | R119-0118    | 119-0118                                                                                                   | Pad - Bumper                   | 10      |                |
| 54      | R85-8960     | 85-8960                                                                                                    | Spacer                         | 2       |                |
| 55      | R325-9       | 01-150-0920,<br>01-178-0818,<br>18-9540,<br>3226-5                                                         | Bolt - 1/2-13 x 2 1/4 Hex Head | 2       |                |

All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.



# Replaces Toro Groundsmaster 4010-D Parts

*Rotary Mower - Model 30446  
Side Deck Lift Arm and Damper*



| Item No | R&R Part No. | OEM Part No.                                                                          | Description                  | Qty Req | Order Quantity |
|---------|--------------|---------------------------------------------------------------------------------------|------------------------------|---------|----------------|
| 57      | R325-5       | 01-150-0250,<br>01-178-0810,<br>19-8000,<br>20-86-AGD,<br>3226-1,<br>325-5,<br>513375 | Bolt - Hex HD 1/2-13 x 1-1/4 | 8       |                |
| 58      | R321-47      | 321-47                                                                                | Screw-Hh                     | 2       |                |
| 59      | R120-0480-03 | 120-0480-03                                                                           | Guide - Hos - RH             | 1       |                |

All original equipment manufacturers names and part numbers are used for identification purposes only, and we are in no way implying that our products are original equipment parts. Prices subject to change without notice.