



NGK Spark Plug - ILFR5B11

RN1637



Replaces

Bosch

FR8MII33X

Specifications

Manufacturer

NGK

Box Quantity

4

Package Quantity

1

Japan Equipment

123 Main St. Apartment 12 Tokyo, 100-0001
987-456-3210

<https://japan.rrproducts.com/>