



NGK Spark Plug - BKR5ES-11

RN2382



Replaces

Autolite	3926
----------	------

Specifications

Manufacturer	NGK
Box Quantity	4
Package Quantity	1

Japan Equipment

123 Main St. Apartment 12 Tokyo, 100-0001
987-456-3210

<https://japan.rrproducts.com/>