



NGK Spark Plug - LZTR5AGP RN3381



Replaces

Autolite	AP5426
Bosch	HR8TPP3002V, HR9SPP300X
Champion	3570, 7032

Specifications

Manufacturer	NGK
Box Quantity	4
Package Quantity	1

Japan Equipment

123 Main St. Apartment 12 Tokyo, 100-0001
987-456-3210

<https://japan.rrproducts.com/>