




NGK Spark Plug - UR5GP

RN3547



Replaces

Autolite	AP23, AP24, AP664
Champion	3018, 3018-2, 7018

Specifications

Manufacturer	NGK
Box Quantity	4
Package Quantity	1

Japan Equipment

123 Main St. Apartment 12 Tokyo, 100-0001
987-456-3210

<https://japan.rrproducts.com/>