



NGK Spark Plug - DPR9EA-9

RN5329



Replaces

Autolite	4162
Champion	8809, 8809-1, RAX92YC
Denso	X27EPR-U9

Specifications

Manufacturer	NGK
Box Quantity	10
Package Quantity	1

Japan Equipment

123 Main St. Apartment 12 Tokyo, 100-0001
987-456-3210

<https://japan.rrproducts.com/>