




NGK Spark Plug - ZFR5FGP RN7098



Replaces

Autolite	AP985
Bosch	FR8HPP30X, FR8LPP302X, FR8LPP30X
Champion	3318, 3318-2

Specifications

Manufacturer	NGK
Box Quantity	4
Package Quantity	1

Japan Equipment

123 Main St. Apartment 12 Tokyo, 100-0001
987-456-3210

<https://japan.rrproducts.com/>