

Replaces Toro Workman 3100 Parts

Traction Unit Steering & Controls





R	Replaces Toro Workman 3100 Parts				
	R&R	Steering & Controls		Qty	Order
No	Part No.	Part No.	Description	Req	Quantity
Guag	es and Cont	rols			
30	R114-3315	114-3315	Solenoid -12 Vdc	1	
31	R94-4208	94-4208	Hourmeter	1	
32	R95-8999	95-8999	Switch - Headlight	1	
34	R151541	R&R ON, LY	Delta Seat Switch - Twist Mount 1 Pole Normally Open	1	
35	R106-6726	106-6726	Steering Pump Assy	1	
36	R27-2360	27-2360	Switch - Key 6 Lead 9/16 Mount	1	
37	R100-4918	100-4918	Diode	1	
Othe	r Parts Avail	able			
70	RMXB180G	106-6672, 112-2923, 119-8829, 133-0577	Milsco Seat XB180 - Grey	2	

Detail Description: The Milsco XB180 bucket seat is designed with a sturdy vacuum formed waterproof vinyl cover that will not crack or peel. Ergonomic foam cushions ensure operator comfort. Features a durable blow molded plastic frame. Allows for an operator presence switch. Central drain hole prevents water build-up. 19 inch high-back seat will replace both original 16in and 19in high-back seats. Seat: 18.75in W x 18.8in H. Grey. Made in U.S.A.
Please note: Due to excessive air freight charges, this item will be shipped ground freight.:

71 R98-1471	93-5212, 94-3500, 98-1471	Steering Wheel Assy - 14 in Incl Cap	1
72 R98-1468	98-1468	Cap - 14" Steering Wheel	1
73 R3234-29	3234-17, 3234-29	Bolt - 5/16-18x1 Serr Hex	10

R	& R ducts	Replaces Toro Work	man 3100 Parts	
	R&R Part No.	Steering & Controls OEM Part No.	Description	Qty Order
	R150848	100-4928, 106-7848, 110-0413, 110-9720, 95-8910	Description Belt-Seat	Req Quantity
78	R2412-133	01-651-0160, 2412-133	Clamp	1
79	R3234-11	3234-11	Bolt - Hex Washer HD	1
80	R3212-4	3212-3, 3212-4, 3212-5	Bolt - Hex HD 7/16-20 x 1 GR5	4
81	R99-7420	100-8493, 99-7420	Plug-Hole	3
82	R150224	106-7847 & 107-7959, 107-7959, 119-0654 & 119-0655, 133-8896, 192-8990 & 92-8991, 92-8990, 92-8990/92-8991, 92-8991	Adjusters - Seat (Set of 2)	2
83	R106-2475	106-2475	Brake Shaft Assy	1
84	R63-3410	63-3410	Screw - Shoulder	2
85	R256-156	256-156, 256-219	Bushing - Flanged	4
86	R302-5	21-6010, 302-11, 302-37, 302-47, 302-5, 302-57, 302-58, 302-6, 31-0300, 32-9660, 60-0800, 62-3880, 92-4181	Fitting - Grease	2

R&R Products	Replaces Toro Workman 3100 Parts				
ltem R&R No Part No.	Steering & Controls OEM Part No.	Description	Qty Req	Order Quantity	
87 R66-3160	33114-020, 43-0110, 48-7710, 66-3160	Bolt - Flanged Hex HD	4		